

well file
2 Nicklas
C NW 1/4 2-9N-55W



BEST IMAGE
AVAILABLE

December 28, 1960

Cronk & Associates Incorporated
Attn: B. Bayouth
410 Columbia Building
Tulsa, Oklahoma

Gentlemen:

Reference is made to your letter of December 20, 1960 stating you have taken over the operations of the S.D. Johnson-Nicklas Lease, Spring Creek Field, Logan County, Colorado.

In answer to your request I have listed below the reports required by our office. For reference I have included the specific rule and page number of our rules and regulations for each requirement.

1. Designation of Agent-Rule 302-Page 10- This is required of all operators in the State, only one copy is needed, and a new form is required only if your agent or address would change. The agent must be an individual.
2. Bonding Requirements-Rule 304-Page 10- Since this lease is patented or private land, a \$2500 bond must be posted on each well.
3. Operator's Monthly Production Report-Rule 308-Page 12- This report is required monthly, beginning in September 1960 in your case, whether or not a well is produced.
4. We also require a weekly report of daily average production. You will find forms enclosed; however, there is no rule in this regard.
5. Mill Levy Return-Rule 309-Page 12- This report must also be submitted monthly; however, the Revenue Department will forward the forms to you. Please read the instructions on the form carefully since this has been revised since the Rules & Regulations were published.



BEST IMAGE
AVAILABLE



Cronk & Associates Incorporated - - Page 2

6. Certificate of Clearance-Rule 311-Page 12- Three copies of this report are required for each of the two wells which our records indicate to be producing, namely, the #2 Nicklas in the C NW 1/4 section 30 and the #4 Nicklas in the C N 1/2 section 30. Please indicate under remarks the effective date of change of ownership.

Although the above are all the reports required, there is another assist you may be able to give us. Last October I wrote S.D. Johnson regarding the Vessels #1 Nicklas located in the NW NW section 30 which I understood he had reentered. Since this is apparently the same lease, perhaps you could help us on the present status of the well. I have enclosed form 6's, Rule 307, Page 11 in case you can fill these out.

I hope the above will answer all your questions; however, if you have any questions please contact us.

Very truly yours,

OILAND GAS CONSERVATION COMMISSION

William R. Smith, Senior Petroleum Engineer

WRS:eh

Enclosures

cc: Department Of Revenue
Attn: Mrs. Hoffshulty
555 Acema Street
Denver 4, Colorado