



July 10, 1959

S. D. Johnson and Flagg Bros.
1517 Denver Club Bldg.
Denver 2, Colo.

Gentlemen:

It has been noticed on the well completion reports (OGCC Form 5) dated June 30, 1959, for wells No. 2 and No. 4 Nicklas, both located in Section 30, Township 9 North, Range 55 West, Spring Creek Field, Logan County, that gas-oil ratio tests have not been taken.

In accordance with Rule 331 of the Rules and Regulations, such a test should be taken within thirty days following completion of each well. Please advise as to the compliance with the above at your earliest convenience.

If there are any questions regarding this matter, or if we can be of assistance, do not hesitate to contact us.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

By

Frank J. Piro, Associate Petroleum Engr.

FJP:cm