

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2025

Submitted Date:

10/28/2025

Document Number:

719500550

**FIELD INSPECTION FORM**

Loc ID 322366 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 51130  
Name of Operator: LOCIN OIL CORPORATION  
Address: 23501 CINCO RANCH BLVD, B244  
City: KATY State: TX Zip: 77494

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
DePaolo, Corey		corey.depaolo@state.co.us	

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 10/24/2025 at approximately 12:15, Compliance Inspector Matthew Morris conducted an on-site audit at LOCIN OIL CORPORATION, FEDERAL-67S104W/21NESW (OWP) at Location ID #322366 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Erosion onto lease road; location is inaccessible.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other				No BMPs

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
During the audit, the following compliance issues were observed: 1) Erosion onto lease road; location is inaccessible.	morrism	10/28/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500553	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7306002">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7306002</a>