

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2025

Submitted Date:

10/23/2025

Document Number:

699507608

FIELD INSPECTION FORM

Loc ID 322159 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 9 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
Santistevan, Brittani		brittani.santistevan@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
, Spills&Remediations		COGCCSpillRemediation@pdce.com	
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209389	WELL	SI	01/01/2018	OW	039-06293	WHITEHEAD 12-16	SI

General Comment:

[Follow up inspection to document # 699507586](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Riser not capped/flagged		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	10/23/2025
Type	TRASH		
Comment:	Trash on location needs to be cleaned up. Unused equipment needs to be removed.		
Corrective Action:	Comply with rule 606	Date:	10/23/2025
Type	OTHER		
Comment:	Stained soil needs to be removed.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	10/23/2025
Type	OTHER		
Comment:	Inadequate stormwater control measures on stockpile of contaminated soil, and under tanks/pump		
Corrective Action:	Implement BMP following good engineering practices to minimize contact with stormwater and precipitation.	Date:	10/23/2025
Type	OTHER		
Comment:	No BOP on well, no well control present. 2 different flanges on wellhead and stripping head, only 4 wellhead bolts installed on wellhead/stripping head.		
Corrective Action:	Install BOP as required by Rule 603.c. Perform BOP test.	Date:	10/23/2025
Type	OTHER		
Comment:	Berm around tanks has significant erosion damage. Berm needs to be repaired		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date:	10/23/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 209389 Type: WELL API Number: 039-06293 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 09/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Workover

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 10/22/25 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Whitehead 12-16 Company Name- Renegade API- 05-039-06293 In Elbert County Colorado. While there, I observed Workover rig. This is a follow up inspection from document # 699507586 Corrective Actions are Delinquent. During this inspection the following possible compliance issues were observed: BOP / well control. Rule 603 c. 10/23/25 Stormwater. Rule 1002.f(2)a. 10/23/25 Trash / Unused equipment. Rule 606. 10/23/25 Stained soil. Rule 1002.(2).D. 10/23/25 Riser. Rule 1105. 10/23/25 Berms. Rule 603 o. 10/23/25 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	10/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404402252	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293713
699507609	Photos/videos/pano	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293707