

From: Colby McKee
 Sent: Monday, November 3, 2025 6:46 AM
 To: Tammy Jones; Ben Mitchell; Lisa Jones; Justin Arinder; Cameron Garrett; Priscilla Shorty; Scott Wagner
 Subject: RE: ALLISON UNIT 116 - INC - 714002113
 Attachments: 3790011341715756141.jpeg; 1237606818114452046.jpeg; 5646418882572799013.jpeg

Bindweed was removed and sprayed, the fence was put in for the land owner.

From: Tammy Jones <tajones@hilcorp.com>
 Sent: Friday, May 2, 2025 9:35 AM
 To: Ben Mitchell <bemitchell@hilcorp.com>; Lisa Jones <ljones@hilcorp.com>; Justin Arinder <jarinder@hilcorp.com>; Cameron Garrett <cgarrett@hilcorp.com>; Colby McKee <cmckee@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Scott Wagner <swagner@hilcorp.com>; Tammy Jones <tajones@hilcorp.com>
 Subject: ALLISON UNIT 116 - INC - 714002113
 Importance: High

Today's Date:	5/2/2025				
Well Name:	ALLISON UNIT 116	Location:	Sec: 20	Twn: 032N	Rng: 0
API Number:	05.067.07243	Footage:	1850' FNL & 880' FWL		
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0501	Justin A
Meter #:			Pipeline:		
INC Number:	714002113	Agency:	ECMC	Inspector:	Corey M
Type of INC:	Written	Photos Required:	Yes	Due Date:	
Issue of Concern:	<p>On 4/28/2025 Reclamation Specialist Corey McDonough conducted a Final Reclamation Inspection Energy Companies Allison Unit 116 Location in La Plata County, Colorado. This is a follow up inspection doc # 714000689. Any Corrective Actions from previous inspections that have not been still applicable.</p> <p>During the inspection the following compliance issues were observed:</p> <ul style="list-style-type: none"> - Final Reclamation (vegetation) - Field Bindweed observed dominating project area. Comply with treat/remove weeds. <p>Location has not met final reclamation vegetation requirements, minimal desirable vegetation was throughout the location. Reseeding efforts are needed. Perimeter fencing remains on location and</p>				

removed per 1004 rules. **Remove perimeter fencing; Comply with Rule 1004. Reseed disturbed areas with seed mixture requested by the surface owner, or a mixture prescribed by the local county NR. Reestablish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall monitor and manage this site until the location meets Rule 1004 standards, including stormwater management.**

Tammy Jones | HILCORP ENERGY COMPANY | San Juan Regulatory | 505.324.5185 | tajones@hilcorp.com

Chad Dunaway
340 Bonita Vista Dr.
Ignacio, CO 81137

September 29, 2025

Colorado Oil and Gas Conservation Commission (COGCC)
c/o Colorado Energy and Carbon Management Commission (ECMC)
1120 Lincoln Street, Suite 801 Denver, Colorado, 80203

Re: Allison Unit 116 Well (API No. 05-067-07243) – Surface Reclamation per Rule 1004

Dear Commissioners,

This letter is written in reference to the Allison Unit 116 (the “Subject Well”) operated by Hilcorp Energy Company, which has been properly plugged and abandoned. I am the owner of the surface property upon which the Subject Well is in Section 20, Range 32N Range 6W, La Plata County CO.

I respectfully request that the surface location and fence of the Subject Well remain in its current state of reclamation and location with no further modification. I intend to utilize the existing surface location for the storage of certain farm equipment and personal belongings, and the current condition of the site is suitable for this purpose.

By submitting this letter, I confirm that I do not desire any further reclamation, surface restoration activities or fence modifications to be performed by HILCORP Energy Company or any other party on the Subject Well location.

Thank you for your attention to this matter. Please let me know if any additional forms, documentation, or acknowledgements are required to process this request.

Sincerely,

Chad Dunaway
Surface Owner

A handwritten signature in black ink, appearing to read 'Chad Dunaway', written over a horizontal line.



