

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404420715

Date Received:
11/03/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Walker, Mandi</u>		<u>mwalker@hilcorp.com</u>
<u>. General</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002113
Inspection Date: 04/28/2025 FIR Submit Date: 05/01/2025 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325961

Location Name: ALLISON UNIT-N32N6W Number: 20SWNW County: _____
Qtrqtr: SWN Sec: 20 Twp: 32N Range: 6W Meridian: N
W
Latitude: 37.004642 Longitude: -107.529837

FACILITY - API Number: 05-067-00 Facility ID: 325961

Facility Name: ALLISON UNIT-N32N6W Number: 20SWNW
Qtrqtr: SWN Sec: 20 Twp: 32N Range: 6W Meridian: N
W
Latitude: 37.004642 Longitude: -107.529837

CORRECTIVE ACTIONS:

1 CA# 204528

Corrective Action: Comply with rule 1004.e, treat/remove weeds. Date: _____

Response: CA COMPLETED Date of Completion: 11/03/2025

Resolved - see attached photos

Operator Comment: _____

ECMC Decision: _____

ECMC Representative: _____

2 CA# 204529

Corrective Action: Remove perimeter fencing; Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 05/15/2025

Response: CA COMPLETED

Date of Completion: 11/03/2025

Operator Comment: Resolved - see attached surface owner letter and photos.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Resolved - see attachment

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones Signed: _____

Title: Ops/Regulatory Tech Date: 11/3/2025 11:52:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404420715	FIR RESOLUTION SUBMITTED
404420717	Resolved Photos

Total Attach: 2 Files