

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404420340

Date Received:  
11/03/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>QB ENERGY</u>		<u>ecmc.inspections@qb-energy.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708907730  
Inspection Date: 10/22/2025 FIR Submit Date: 10/27/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: QB ENERGY OPERATING LLC Company Number: 10844  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**LOCATION** - Location ID: 445862

Location Name: Mesa Number: P24-697 County: \_\_\_\_\_  
Qtrqtr: SESE Sec: 24 Twp: 6S Range: 97W Meridian: 6  
Latitude: 39.502986 Longitude: -108.161794

**FACILITY** - API Number: 05-045-00 Facility ID: 445862

Facility Name: Mesa Number: P24-697  
Qtrqtr: SESE Sec: 24 Twp: 6S Range: 97W Meridian: 6  
Latitude: 39.502986 Longitude: -108.161794

**CORRECTIVE ACTIONS:**

**1** CA# 208957

Corrective Action: Comply with CECMC Rule 602 Date: 11/03/2025

Response: CA COMPLETED Date of Completion: 10/31/2025

Operator Comment: Capped and covered all open ports and piping on location to comply with ECMC rules 602.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 208958

Corrective Action: Comply with CECMC Rule 606

Date: 11/26/2025

Response: CA COMPLETED

Date of Completion: 10/31/2025

Operator Comment: Removed unused chemical tank to comply with ECMC rule 606.

ECMC Decision:

ECMC  
Representative:

3 CA# 208959

Corrective Action: Comply with CECMC Rule 608

Date: 11/03/2025

Response: CA COMPLETED

Date of Completion: 10/31/2025

Operator Comment: Installed rain caps on all PRV and rupture disc vent lines to comply with ECMC rules 608.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed:

Title: Compliance

Date: 11/3/2025 10:16:48 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404420340	FIR RESOLUTION SUBMITTED
404420346	Cattle Panel
404420347	Cattle Panel
404420349	Installed BP
404420351	Rain Cap 1
404420353	Rain Cap 2

Total Attach: 6 Files