

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2025

Submitted Date:

11/06/2025

Document Number:

719200391

## FIELD INSPECTION FORM

Loc ID 313181 Inspector Name: Gaasche, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10255  
 Name of Operator: QUICKSILVER RESOURCES INC  
 Address: 801 CHERRY ST - #3700 UNIT 19  
 City: FT WORTH State: TX Zip: 76102

**Findings:**

- 4 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Cindy Keister	(817) 665-5572	ckeister@qrinc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270286	WELL	PA	12/18/2009	GW	081-07159	CULVERWELL 3-21	RI
313181	LOCATION	CL			-	CULVERWELL-67N93W 3NENW	RI

**General Comment:**

On 10/29/2025, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at Quicksilver Resources Inc's CULVERWELL-67N93W/3NENW location in Moffatt County, Colorado.

It was observed in this inspection that reclamation has not been completed pursuant to 1004 requirements.

The following compliance issues were observed during this inspection:

- Utility equipment remaining
- Access road unreclaimed
- Weeds
- Uniformity

Refer to the Reclamation and COGCC Comments section of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

**Inspected Facilities**

Facility ID: 270286 Type: WELL API Number: 081-07159 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 313181 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Conduct reclamation on the location/road in accordance with 1004 rules including, but not limited to: removal of utility equipment, removal of gravel, compaction alleviation, recontour/regrade and establish vegetation with total perennial, non-invasive uniform plant cover of at least 80% of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district.

Comply with Rule 1002.f and ensure erosion controls are implemented to stabilize the seeded soil.

Comply with Rules 1004.e and 606.c: Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Ongoing stormwater and weed management required until Final Reclamation has passed.

Overall Final Reclamation **Fail** Well Release on Active Location  Multi-Well Location

**ECMC Comments**

Comment	User	Date
<p><b>RECLAMATION COMMENTS:</b>                      Records show well was P&amp;Ad 12/18/2009 by Pioneer Natural Resources USA Inc (Form 6s 1666419). Location/Well was transferred to Foundation Energy Management in 2010, and then to Quicksilver Resources Inc on 2/23/2023 (Form 10 #402518194).</p> <p>The location appears to be used by horses and is primarily composed of crested wheatgrass. Vegetation is patchy throughout the location and uniformity is not evident. Scotch thistle, a List B noxious weed species, was observed throughout the location. It does not appear as though weeds have been managed in 2025.</p> <p>Utility equipment that is no longer in use remains at the location. Utility equipment is associated with the O&amp;G Location for O&amp;G operations, and the corrective action requirements for removal remains applicable. It is the ECMC's expectation that the Operator will coordinate with the equipment's owner for removal.</p> <p>Access roads have not been removed or reclaimed; gravel and compaction is evident and ulverts remain along the road. The access road to the CULVERWELL-67N93W/3NENW did not pre-exist the location. It is noted that the access road was utilized for both the Culverwell 3-21 and the Walker 3-2 Locations. Both Operators share responsibility for reclamation of the access road. After review of records, it has been determined that Quicksilver is responsible for the reclamation of the section of access road from the Culverwell 3-21, to the Walker 3-2 Location; and SWN is responsible for the reclamation of the remaining access road that travels Northeast from the Walker 3-2 Location. Refer to inspection #696206200 and #696206202 for additional details. It is ECMC's expectation that both Operators will coordinate to resolve the outstanding compliance issues.</p>	gaaschee	11/06/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719200392	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7320769">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7320769</a>