

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404426867

Date Received:
11/06/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>	<u>970-285-9377</u>	<u>COGCCInspectionReports@terraep.com</u>
<u>Coleman, Chris</u>		<u>chris.coleman@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 707801597
Inspection Date: 05/15/2025 FIR Submit Date: 05/16/2025 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335264

Location Name: GIBSON GULCH UNIT-66S91W Number: 30SENW County: _____
Qtrqr: SENW Sec: 30 Twp: 6S Range: 91W Meridian: 6
Latitude: 39.499301 Longitude: -107.598441

FACILITY - API Number: 05-045-00 Facility ID: 335264

Facility Name: GIBSON GULCH UNIT-66S91W Number: 30SENW
Qtrqr: SENW Sec: 30 Twp: 6S Range: 91W Meridian: 6
Latitude: 39.499301 Longitude: -107.598441

CORRECTIVE ACTIONS:

1 CA# 204893

Corrective Action: Keep location free of equipment not used on lease or provide proper and approved documentation for stored equipment.

Date: 11/05/2025

Response: CA COMPLETED Date of Completion: 11/05/2025

Operator Comment: The landowner has removed the tires that were were being used as feed bunks for cattle. Please see attached photos documenting that there is no landowner equipment remaining within the existing permitted boundary area of this well pad. This corrective action is complete.

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The landowner has removed the tires that were were being used as feed bunks for cattle. Please see attached photos documenting that there is no landowner equipment remaining within the existing permitted boundary area of this well pad. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 11/6/2025 4:03:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404426940	Photo documentation - old tires (feed bunks) removed
404426941	Photo documentation - old tires (feed bunks) removed
404426943	Photo documentation - old tires (feed bunks) removed

Total Attach: 3 Files