



00261390



SEP 27 1965  
OIL & GAS  
CONSERVATION COMMISSION

# CONTINENTAL OIL COMPANY

P. O. Box 1621  
Durango, Colorado  
September 24, 1965

Mr. D. V. Rogers, Director  
Oil and Gas Conservation Commission  
State of Colorado  
1525 Sherman Street  
Denver, Colorado 80203

Re: SPRAGUE BROS. NO. 1, RED LION  
FIELD, SE/4 SE/4 SEC. 18, T10S,  
R47W, SEDGWICK COUNTY, COLORADO

Dear Mr. Rogers:

Continental Oil Company previously acquired approval to conduct a multi-phase flow test on the referenced well. The outlined procedure was to conduct a flow test and buildup, with a repeat cycle, wherein a total of 40 to 50 MMCF of gas would be flared.

The approved test has been conducted; however, because of drilling mud influx during these tests, the data are not sufficiently accurate to allow us to obtain the desired information with respect to reservoir limits.

Therefore, Continental Oil Company requests permission to conduct a repeat test since the later data indicate the well bore to have cleaned up. An additional flow period should provide sufficient accurate data to complete our analysis.

Very truly yours,

H. D. Haley  
District Manager  
Durango District  
Production Department

HW/slf

cc: E. A. Austin, Continental Oil Company, Denver, Colorado

DVR	<input checked="" type="checkbox"/>
WRS	<input type="checkbox"/>
HHM	<input type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
FJP	<input type="checkbox"/>
JJD	<input type="checkbox"/>
FILE	<input type="checkbox"/>