

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2025

Submitted Date:

11/17/2025

Document Number:

719200441

FIELD INSPECTION FORM

Loc ID 314518 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 5 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Olson, Andrew		AndrewOlson@chevron.com	All NW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228897	WELL	PA	08/21/2023	OW	103-05895	WILSON CREEK UNIT 25	RI
314518	LOCATION	CL			-	WILSON CREEK UNIT-63N94W 27SWSE	RI

General Comment:

On 11/14/2025, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at Chevron USA Inc's WILSON CREEK UNIT-63N94W/27SWSE location in Rio Blanco County, Colorado.

The following compliance issues were observed during this inspection:

- Stormwater
- Trash and debris

Refer to the Good Housekeeping, Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment: Wooden stakes, twine, and other debris and trash is scattered throughout the location. Removal is required.

Corrective Action: Comply with Rule 606.d. and remove trash/debris.

Date: 11/24/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 228897 Type: WELL API Number: 103-05895 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 314518 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

The location and access road have been recontoured, decompacted and reclaimed. The location has been reseeded recently; vegetation establishment is apparent throughout the location. Vegetation is primarily composed of Rocky Mountain penstemon and perennial grasses, such as western wheatgrass and thickspike wheatgrass. Undesirable plant species such as Scotch thistle, prickly Russian thistle and pigweed is present in tertiary amounts throughout the location. Weeds appear to have been managed in 2025; ongoing weed management is necessary until the location receives a passing final reclamation inspection. A follow-up inspection will be conducted during future growing seasons to determine progression towards 1004 reclamation requirements.

Corrective Action: Date: _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Straw wattles throughout the location are overtopped with sediment or in disrepair and no longer functioning as intended in some areas throughout the location. Erosion and degradation is occurring in some areas. Stormwater BMPs require maintenance. See photos for more detail.

Corrective Action: **Comply with 1002.f.**

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719200442	Inspection Photos	https://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7336048