

Inspection Photos
Location Name: Joe Brophy 11-31 4N46W
API Number: 125-10212



1. Lease sign at well location.




2. View of wellhead.

Inspection Photos
Location Name: Joe Brophy 11-31 4N46W
API Number: 125-10212



3. Lease sign at gathering location.



4. Calibration/Test Log inside Meter Shed.