

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2025

Submitted Date:

11/25/2025

Document Number:

713302360

FIELD INSPECTION FORM

Loc ID 305813 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282562	WELL	SI	06/01/2025	GW	123-23516	Matsushima 4-19X	SI

General Comment:

[well site inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 282562 Type: WELL API Number: 123-23516 Status: SI Insp. Status: SI

Producing Well

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/23/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: submit report

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Audit of scout card and related documents</u> <u>Routine inspection</u>	kesterm	11/25/2025
<u>This inspection does not nullify any orders or NOAV from the ECMC</u>		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302361	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7349873