

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/24/2025

Submitted Date:

11/24/2025

Document Number:

716301749

FIELD INSPECTION FORM

Loc ID 308410 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
B WARD, GIENA		gward@ogrisop.com	All Inspections
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271278	WELL	PR	05/01/2021	GW	071-07990	NEW ELK 35-13	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Signs/Marker:

Type			
Comment:	NO API POSTED ON LOCATION.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.		Date: 12/02/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	30 BBL PRODUCED WATER/ USED OIL TANK		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	ATTACHED IS THE FORM 4 VACUUM		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 271278 Type: WELL API Number: 071-07990 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/30/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [PHOTO 5: OILY WASTE IN COMPRESSOR SKID FROM LEAKING EQUIPMENT.](#)

Corrective Action: **DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO REMOVE OILY WASTE IN SKID. FIXING LEAKS BY 12-28-2025.**

Date: 12/28/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404448652	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7346633
716301751	FORM 4 SUNDRY (VACUUM)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7346630
716301752	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7346631