

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404457330

Date Received:
12/02/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Karen Adams	3039161170	Adams@kt-res.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 715501163

Inspection Date: 01/14/2025 FIR Submit Date: 01/14/2025 FIR Status: _____

Inspected Operator Information:

Company Name: KT RESOURCES LLC Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

LOCATION - Location ID: 316241

Location Name: WRD WYATT-62N97W Number: 36NENE County: RIO BLANCO

Qtrqr: NENE Sec: 36 Twp: 2N Range: 97W Meridian: 6

Latitude: 40.103480 Longitude: -108.220058

FACILITY - API Number: 05-103-00 Facility ID: 259422

Facility Name: WRD WYATT Number: 36-14

Qtrqr: NENE Sec: 36 Twp: 2N Range: 97W Meridian: 6

Latitude: 40.103480 Longitude: -108.220058

CORRECTIVE ACTIONS:

1 CA# 201753

Corrective Action: Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.

Date: 01/25/2025

Response: CA COMPLETED Date of Completion: 02/03/2025

Operator Comment: Labels replaced

ECMC Decision: _____

ECMC Representative: _____

3 CA# 201755

Corrective Action: Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.

Date: 01/22/2025

Response: CA COMPLETED

Date of Completion: 02/03/2025

Operator Comment: Mowed location

ECMC Decision: _____

ECMC Representative: _____

4 CA# 201756

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 06/07/2023

Response: CA COMPLETED

Date of Completion: 02/03/2025

Operator Comment: Bladed location

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karen Adams

Signed: _____

Title: Manager

Date: 12/2/2025 9:33:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404457330	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files