



99999999

CO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- (115 - 06002)		LEASE NAME: Ham 2	
LOCATION: NW SW 17-10N-47		OPERATOR: Lyte E. Johnson	
DATE: 4-2-96		INSPECTOR: Ed Binkley	
Insp. Type: SR	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F Viol.: Y <input checked="" type="radio"/> N NOV: Y <input type="checkbox"/> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	Conoco sign at site	
Pits (Reserve/Production) (Rule 902, 903, 904)	4" Pipe line header at site.	
Fences (Rule 604.C.(3), 1003.A)	fencing and 100'-2" flowline	
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		



00261367

CORRECTIVE ACTION REQUIRED: Restore site or submit landowner release for reclamation of site.

Date Corrective Action Required By: 4-30-96 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

APR 18 1996