

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/01/2025

Submitted Date:

12/01/2025

Document Number:

708907916

**FIELD INSPECTION FORM**

Loc ID 324207 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264674	WELL	SI	07/01/2025	GW	045-08930	PUCKETT 41-36	SI

**General Comment:**

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

**Inspected Facilities**

Facility ID: 264674 Type: WELL API Number: 045-08930 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17

Date: 12/31/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 12/01/2025 at approximately 12:56 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop inspection/audit of QB ENERGY OPERATING LLC PUCKETT 41-36 Location # 324207 in Garfield County Colorado.                      Location is within High Priority/Density/Black Bear Habitat areas.</p> <p>During this desktop inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - Well lacks wellbore diagram - Comply with Rule 420 with a CA date of 12/31/2025</p> <p>A follow up on this desktop inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of desktop inspection/audit report.</p>	smelserw	12/01/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404454693	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7354262">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7354262</a>