

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404473784

Date Received:
12/15/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>
<u>Smelser, Wayne</u>		<u>wayne.smelser@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100205
Inspection Date: 01/17/2025 FIR Submit Date: 01/27/2025 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 418623

Location Name: Farris Number: RWF 34-31 County: _____
Qtrqtr: SESW Sec: 31 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.475105 Longitude: -107.929298

FACILITY - API Number: 05-045-00 Facility ID: 418623

Facility Name: Farris Number: RWF 34-31
Qtrqtr: SESW Sec: 31 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.475105 Longitude: -107.929298

CORRECTIVE ACTIONS:

2 CA# 202009

Corrective Action: Comply with 606 Requirements: The storage or placement of equipment and supplies not necessary for use on location is prohibited. Date: _____

Response: CA COMPLETED Date of Completion: 12/09/2025

Operator Comment: Since the inspection conducted on January 17, 2025 (doc #718100205), TEP has worked diligently to notify the surface owner and to assist in removing all equipment from the pad to areas outside of the permitted oil and gas location boundary. TEP submitted FIRR doc# 404093652 on 2/13/25 providing an update of efforts to communicate with the surface owner and request their cooperation in removing their equipment from the location. The surface owner agreed to move personal items stored on the pad to areas outside of the permitted oil and

gas location boundary. All equipment and materials that were placed on the location by the surface owner have now been removed (see attached photos). This corrective action has been completed.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Since the inspection conducted on January 17, 2025 (doc #718100205), TEP has worked diligently to notify the surface owner and to assist in removing all equipment from the pad to areas outside of the permitted oil and gas location boundary. TEP submitted FIRR doc# 404093652 on 2/13/25 providing an update of efforts to communicate with the surface owner and request their cooperation in removing their equipment from the location. The surface owner agreed to move personal items stored on the pad to areas outside of the permitted oil and gas location boundary. All equipment and materials that were placed on the location by the surface owner have now been removed (see attached photos). This corrective action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 12/15/2025 3:52:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404473944	Surface Owner Equipment Removed from Interim Reclaim Area
404473946	Surface Owner Equipment Removed from Interim Reclaim Area
404473948	Surface Owner Equipment Removed from Interim Reclaim Area

Total Attach: 3 Files