

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

12/18/2025

Document Number:

718101011

FIELD INSPECTION FORM

Loc ID 334495 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334445	LOCATION	AC			-	Griffith 11-2 Pad	RI
334495	LOCATION	AC			-	GRIFFITH-69S94W 11NWNE	RI

General Comment:

On 12/16/2025, Western Reclamation Work Lead Trujillo conducted an inspection at Laramie Energy LLC's Griffith/11-2 Pad location in Mesa County, Colorado.

It appears two Locations have been created for this site; with 12 wells being associated with the Griffith/11-2 Pad (#334445), and the remaining 3 being associated with the GRIFFITH-69S94W/11NWNE (#334495)

Location is within the following High Priority Habitats: Aquatic Cutthroat Trout Designated Crucial Habitat Elk Winter Concentration Area

Location is within close proximity to the following High Priority Habitats: Aquatic Native Species Conservation Waters; Aquatic Sportfish Management Waters.

The following compliance issues were observed during this inspection:

- Good Housekeeping
- Public Access restriction requirements
- Flowline/Pipeline registration requirements

Refer to the Location, Reclamation and Stormwater sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Label with operator and capacity information on tank 077/0542/001 is peeling/becoming illegible. Maintenance advised.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-242-1234 / 970-248-0497 / 1-800-891-6194		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Location appears to be in use as a "Disc Golf Course"; disc golf cages observed within the cut and fill areas on the west and northeast end of the Location. Skids/platforms and a bench also observed on the southwest corner of the working pad surface. A 502.b variance pursuant to Rule 606.a.(2) has not been approved to permit this; the storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, Chemicals, drums, totes, Containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.		
Corrective Action:	Comply with Rule 606		Date: 12/25/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	#		corrective date
Comment:	Pipeline leading north and south of the Location evident; pipeline appears to be off-location flowlines / flowline system. Unable to find records that the pipeline has been registered.		
Corrective Action:	Comply with 1101 registration requirements.		Date: 12/25/2025
Type:	#		
Comment:	The Oil and Gas Location appears to be accessed by the public, or unauthorized persons, for use as a "Disc Golf Course".		

Corrective Action:	Per rule 608.c install appropriate and adequate protections to prevent access by the public.	Date:	01/18/2026
--------------------	--	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 334445 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 334495 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment No waste or debris observed on the interim or production areas of the Location.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment Refer to the "Good Housekeeping" section of this report regarding equipment not necessary for production.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? In
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? In Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? I

Comment No immediate reclamation concerns observed at time of inspection. Noxious weeds not apparent. Vegetation consists predominantly of perennial species such as Brome grass, Intermediate, Western and Crested Wheatgrass; vegetation appears to be progressing towards 1003 standards

Corrective Action Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						South end of Location.
Ditches						
Compaction						
Berms						
Gravel						

Comment: No immediate stormwater concerns observed at time of inspection. Gravel is becoming sparse within areas of the Location and tracking is becoming evident.
Continue to monitor and manage SW BMPs on the Location, and ensure controls remain in proper functioning condition.

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718101013	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7383112