

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2025

Submitted Date:

12/20/2025

Document Number:

693809100

FIELD INSPECTION FORM

Loc ID 316835 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10841
Name of Operator: AMERICAN HELIUM LLC
Address: 23501 CINCO RANCH BLVD, B244
City: KATY State: TX Zip: 77494

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Harrison, Trish		trish.harrison@coolskyenergy.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Vick, Greg		gregvick@3gc.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265250	WELL	TA	02/01/2025	GW	113-06115	ANDY'S MESA FEDERAL 30	TA

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On December 18, 2025, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for American Helium LLC 10841 on the Andy's Mesa Federal #30 well, API# 05-113-06115, in San Miguel County, Colorado.

Form 42 - Start of Plugging Operations Doc#404467107 was recieved 12/10/2025. On 12/18/2025 No evidence of plugging operations were observed. Wellhead still intact in TA status.

During the inspection/audit, the following compliance issues were observed:

- 1) A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 per form 42 instructions. CA date 12/22/2025
- 2) Guy line anchors not marked - CA per Rule 1003.a, CA date 1/5/2026
- 3) Missing bird protectors on open ended flowline at tank battery - CA per Rule 608.b.(7), CA date 12/26/2025

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location

Lease Road:			
Type	Main		
comment:	Hwy 141		
Corrective ActionL			Date:
Type	Access		
comment:	R25		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign on meter housing		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Dissconnected with blind flange		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Dissconnected with bull plug		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1	
Comment:	Flowline inside tank berms open ended with no bird protection screen.	
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.	Date: <u>12/26/2025</u>
Type: Deadman # & Marked	# 4	
Comment:	Guy line anchor on NW corner not marked.	
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date: <u>01/05/2026</u>

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	Open Top		38.054988,-108.657149
Comment:	Screened open top blowdown tank inside metal berms.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 265250 Type: WELL API Number: 113-06115 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Form 42 - Start of Plugging Operations Doc#404467107 was recieved 12/10/2025.

Corrective Action: A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 per Form 42 instructions.

Date: 12/22/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>Form 42 - Start of Plugging Operations Doc#404467107 was recieved 12/10/2025. On 12/18/2025 No evidence of plugging operations were observed. Wellhead still intact in TA status. Equipment still on location. Gas meter and separator are disconnected and blinded. During the inspection/audit, the following compliance issues were observed:</p> <p>1) A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 per form 42 instructions. CA date 12/22/2025</p> <p>2) Guy line anchors not marked - CA per Rule 1003.a, CA date 1/5/2026</p> <p>3) Missing bird protectors on open ended flowline at tank battery - CA per Rule 608.b.(7), CA date 12/26/2025</p>	browninc	12/20/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404482909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7387032
693809103	Inspection photos 12/18/2025	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7387025