

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 46-21

Location ID: 323869



Photo # 5346 From entrance to location



Photo # 5347 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 46-21

Location ID: 323869



Photo # 5348 Location



Photo # 5349 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 46-21

Location ID: 323869



**Illegible Battery Sign – Photo #00078 From inspection/audit
719500308 conducted on 08/08/2025**

**Photo # Photo # 2173 From inspection/audit 708907542
conducted on 09/24/2025 - Illegible Battery Sign**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 46-21

Location ID: 323869



Photo # 5810 From inspection/audit 708907638 conducted on 10/09/2025 - Illegible Battery Sign

Photo # 5350 Illegible Battery Sign

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 46-21

Location ID: 323869



Illegible Wellhead Sign – Photo #00075 From inspection/audit 719500308 conducted on 08/08/2025



Photo # 2174 From inspection/audit 708907542 conducted on 09/24/2025 - Illegible Wellhead Sign

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL MV 46-21

Location ID: 323869




Photo # 5811 From inspection/audit 708907638 conducted on 10/09/2025 - Illegible Wellhead Sign

Photo # 5351 Illegible Wellhead Sign