

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2025

Submitted Date:

12/23/2025

Document Number:

719500750

FIELD INSPECTION FORM

Loc ID 312389 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 29470
Name of Operator: FEES JR AND SON OIL & GAS* WALTER S
Address: 2516 FORESIGHT CIRCLE RM #10
City: GRAND JUNCTION State: CO Zip: 81505

Findings:

- 15 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Fees, Walter		fwalter8@bresnan.net	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221456	WELL	PR	09/01/2025	GW	077-08057	BAR-X 32-1	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 12/16/2025 at approximately 13:00, Compliance Inspector Matthew Morris conducted an on-site audit at FEES JR AND SON OIL & GAS* WALTER S, BAR-X-68S104W/32SENE at Location ID #312389 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign posted.		
Corrective Action:	Install battery sign to comply with CECMC Signs and Markers Rules.	Date:	01/24/2026
Type	TANK LABELS/PLACARDS		
Comment:	No tank labels posted on plastic AST.		
Corrective Action:	Install required labels on AST to comply with CECMC Signs and Markers Rules.	Date:	01/24/2026

Emergency Contact Number:

Comment: 911/(970)242-2044

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored supplies near separator.		
Corrective Action:	Remove stored supplies from location.	Date:	12/31/2025
Type	WEEDS		
Comment:	Weeds present in secondary containment for plastic AST.		
Corrective Action:	Remove weeds from location.	Date:	12/31/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type:		#		corrective date
Gas Meter Run		# 1		
Comment:				
Corrective Action:			Date:	
Bird Protectors		# 1		
Comment:				
Corrective Action:			Date:	

Type: Deadman # & Marked	# 1	
Comment:	Unmarked deadman on location.	
Corrective Action:	Install required deadman marker to comply with CECMC Rules.	Date: 01/07/2026
Type: Horizontal Heated Separator	# 1	
Comment:	Leak on pressure monitoring tubing inside separator housing.	
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer's recommended specifications per Rule 608.e.	Date: 12/24/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PLASTIC AST		,
Comment:	Missing tank cover on AST poses a wildlife entry hazard.				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Engineer, operate, and maintain equipment within the manufacturer's recommended specifications per Rule 608.e.				Date: 12/29/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Weeds present in secondary containment. Refer to CA in Housekeeping section.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221456 Type: WELL API Number: 077-08057 Status: PR Insp. Status: PR

Producing Well

Comment: [Last Production Casing test performed March 2022.](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						
		Other	Fail			No BMPs installed at water drainage/crossing
Compaction						

Comment: Insufficient erosion controls at water drainage/stream crossing on access road to location. No BMPs installed.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved. Install or repair required BMPs.

Date: 01/08/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <ul style="list-style-type: none"> 1) No battery sign posted 2) No labeling on plastic AST 3) Weeds present in secondary containment for plastic AST 4) Stored supplies on location 5) Unmarked deadman 6) Leak on pressure monitoring tubing on separator 7) Missing cover on plastic AST poses a wildlife entry hazard 8) Stormwater; refer to Stormwater section <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrism	12/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404485736	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389883
719500751	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389879
719500752	Leak in Separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7389880