

FORM
17
Rev
11/20

State of Colorado
Energy & Carbon Management Commission



Document Number:
404490313

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

BRADENHEAD TEST REPORT

Step 1. Before opening any valves, record all tubing and casing pressures as found.
 Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://ecmc/reg.html#/opguidance>
 Step 3. Conduct Bradenhead test.
 Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.
 Step 5. Submit sample analytical results via Form 43.

1. ECMC Operator Number: 72400 3. BLM Lease No: _____
 2. Name of Operator: PUBLIC SERVICE COMPANY OF COLORADO
 4. API Number; 05-077-08238-00 5. Multiple completion? Yes No
 6. Well Name: ASBURY STORAGE UNIT-FED Number: 11
 7. Location (QtrQtr, Sec, Twp, Rng, Meridian): SENE,14,9S,101W,6
 8. County MESA 9. Field Name: ASBURY CREEK
 10. Minerals: Fee State Federal Indian

11. Date of Test: 12/29/2025
 12. Well Status: Flowing
 Shut In Gas Lift
 Pumping Injection
 Clock/Intermitter
 Plunger Lift
 13. Number of Casing Strings:
 Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: <u>760</u> Fm: _____	Tubing: _____ Fm: _____	Prod Csg <u>18</u> Fm: _____	Intermediate Csg: _____	Surf. Csg <u>18</u>
-------------------------------	---------------------------------	----------------------------	---------------------------------	----------------------------	------------------------

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.
 Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper
 Describe fluid type in "Bradenhead Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
00:00	760		18		DOWN TO 0	
05:00	760		18		WHISPER	
10:00	760		18		WHISPER	
15:00	760		18		WHISPER	
20:00	760		18		WHISPER	
25:00	760		18		WHISPER	
30:00	760		18		WHISPER	
REQUIRED - Instantaneous Bradenhead Pressure at End of Test: <u>2</u> PSIG						

INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H₂O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:	
Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	00:00							
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	05:00							
	10:00							
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black Other:(describe) _____	15:00							
	20:00							
	25:00							
	30:00							
REQUIRED - Instantaneous Intermediate Casing Pressure at End of Test: _____							PSIG	

Comments: This is an observation well.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Nolan Britain Title: Operator Phone: (970) 2608975

Signed: Drew Tedford Title: Sr Engineer Date: 12/30/2025

Witnessed By: _____ Title: _____ Agency: _____