

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

RECEIVED



1 duplicate for Patented and Federal lands.
1 triplicate for State lands.

5. LEASE DESIGNATION & SERIAL NO.

OCT - 9 1984
COLO. OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL GAS WELL OTHER SI Oil Well

7. UNIT AGREEMENT NAME
Big Sandy

2. NAME OF OPERATOR
Okmar Oil Company

8. FARM OR LEASE NAME
Budin 27778

3. ADDRESS OF OPERATOR
633-17th Street, Suite 2160, Denver, Colorado 80202

9. WELL NO.
13

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1960'FNL & 450'FEL of irregular Section 2, T8N, R55W
At proposed prod. zone

10. FIELD AND POOL, OR WILDCAT
Big Sandy

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

same

Sec. 2, T8N, R55W

14. PERMIT NO.
78 72

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4369'GR

12. COUNTY
Logan

13. STATE
Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF PULL OR ALTER CASING
FRACTURE TREAT MULTIPLE COMPLETE
SHOOT OR ACIDIZE ABANDON
REPAIR WELL CHANGE PLANS
(Other)

WATER SHUT-OFF REPAIRING WELL
FRACTURE TREATMENT ALTERING CASING
SHOOTING OR ACIDIZING ABANDONMENT*
(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work September 10-12, 1984

* Must be accompanied by a cement verification report.

The subject well was plugged and abandoned as follows:

1. Filled 4 1/2" casing with sand to 5200' (PBSD: 5459') and set a 5 sack cement plug on top of sand.
2. Cut off and recovered 4486' of 4 1/2" casing.
3. Filled hole with mud.
4. Set a 15 sack cement plug in and out of bottom of 8 5/8" surface casing @ 157'KB.
5. Set a 10 sack cement plug in top of surface casing to within four feet of ground level.
6. Cut off surface casing below plow depth and welded on cap.

| |
|-----|
| WRS |
| FIP |
| IP |
| IR |
| LR |
| CR |
| EO |

EXHAUSTED
OIL WELL

19. I hereby certify that the foregoing is true and correct

SIGNED J. Roy White

TITLE Western Operations Manager DATE October 8, 1984

(This space for Federal or State office use)

APPROVED BY William Smith

TITLE DIRECTOR
O & G Cons. Comm.

DATE OCT 29 1984

CONDITIONS OF APPROVAL, IF ANY:

T 1