

# BOHRER 2B-19H-E368 (12338444\_FL): Abandon in Place Layout

40.214451, -105.052447

SWNW Sec. 19 T3N, R68W, 6th PM

Weld County, Colorado

Crestone Peak Resources Operating (10633)

Flowline Unique OperFeatID	Line Type	Start Location Latitude	Start Location Longitude	End Location Latitude (Cut Point)	End Location Longitude (Cut Point)	Segment Length (ft)	Segment	Abandonment Type
12338444_FL	Multiphase	40.214451	-105.052447	40.214192	-105.051621	240	Blue	Abandon in Place



# BOHRER 2D-19H-E368 (12338450\_FL): Abandon in Place Layout

40.214396, -105.052448

SWNW Sec. 19 T3N, R68W, 6th PM

Weld County, Colorado

Crestone Peak Resources Operating (10633)

Flowline Unique OperFeatID	Line Type	Start Location Latitude	Start Location Longitude	End Location Latitude (Cut Point)	End Location Longitude (Cut Point)	Segment Length (ft)	Segment	Abandonment Type
12338450_FL	Multiphase	40.214396	-105.052448	40.214082	-105.051629	250	Blue	Abandon in Place



# BOHRER 2F-19H-E368 (12338447\_FL): Abandon in Place Layout

40.214342, -105.052449

SWNW Sec. 19 T3N, R68W, 6th PM

Weld County, Colorado

Crestone Peak Resources Operating (10633)

Flowline Unique OperFeatID	Line Type	Start Location Latitude	Start Location Longitude	End Location Latitude (Cut Point)	End Location Longitude (Cut Point)	Segment Length (ft)	Segment	Abandonment Type
12338447_FL	Multiphase	40.214342	-105.052449	40.213975	-105.051633	260	Blue	Abandon in Place



# BOHRER TRUST 21-19 (12336861\_FL): Abandon in Place Layout

40.217697, -105.053049

NWNW Sec. 19 T3N, R68W, 6th PM

Weld County, Colorado

Crestone Peak Resources Operating (10633)

Flowline Unique OperFeatID	Line Type	Start Location Latitude/Longitude	End Location Latitude, Longitude (Cut Point)	Approx. Length to Decommission (ft)	Segment	Abandonment Type
12336861_FL	Multiphase	40.217697, -105.053049	40.2143, -105.0516	2320	Blue	Abandon in Place

