

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

RECEIVED

FEB 21 1968



File in duplicate for Patented and Federal lands. File in triplicate for State lands.

COLO. OIL & GAS CONS.

5. LEASE DESIGNATION AND SERIAL NO. COMM.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [ ] OTHER [ ]
2. NAME OF OPERATOR PAT'S POWER TONGS, INC.
3. ADDRESS OF OPERATOR Box 702, Grand Junction, Colorado 81501
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 3299' FSL, 1948' FWL (C E/2 Lot 9, Sec. 5 ) At proposed prod. zone
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4396' K.B.
7. UNIT AGREEMENT NAME Liberty "J" Sand
8. FARM OR LEASE NAME MALLO
9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Liberty
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S.5, T.8N., R.54W.
12. COUNTY OR PARISH Logan 13. STATE Colo.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF [ ] PULL OR ALTER CASING [ ] WATER SHUT-OFF [ ] REPAIRING WELL [ ]
FRACTURE TREAT [ ] MULTIPLE COMPLETE [ ] FRACTURE TREATMENT [ ] ALTERING CASING [ ]
SHOOT OR ACIDIZE [ ] ABANDON [ ] SHOOTING OR ACIDIZING [ ] ABANDONMENT [X]
REPAIR WELL [ ] CHANGE PLANS [ ] (Other) [ ]
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work Compl. 1-23-68

LU-5

Dumped 3 bbls of sand and filled 5 1/2" from 5398' to 5280' depth. Set 15 sack cement plug from 5280' to 5150' depth.

Shot off 5 1/2" casing at 3900' depth and pulled.

Filled hole with heavy mud from 5150' to 225' depth. Set 10 sack cement plug over base of 9-5/8" from 225' to 195' depth.

Filled casing with heavy mud from 195' to approx. 15 ft. below bottom of cellar. Welded on steel plate at top of surface casing. Filled cellar with rocks and dirt and topped off with top soil.

Plugged & Abandoned 1-23-68

Table with 2 columns and 5 rows: DVR, FJP, HWA, JAM, JJD. Includes handwritten 'Ex O.I. Prod.' and checkmarks.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Agent Pat's Power Tongs DATE 2-20-68

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Director DATE 2/21/68

CONDITIONS OF APPROVAL, IF ANY: [Handwritten notes]

T