

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404505696

Date Received:
01/14/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 200665
Name of Operator: FORTRESS DEVELOPMENT SOLUTIONS LLC
Address: 4407 W 29TH STREET
City: GREELEY State: CO Zip: 80634

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Dilka, Tyson	970-539-9354	tdilka@stelbar.com
		jshawver@stelbar.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201890
Inspection Date: 01/02/2025 FIR Submit Date: 01/06/2025 FIR Status:

Inspected Operator Information:

Company Name: STELBAR OIL CORP INC Company Number: 82470
Address: 1625 N WATERFRONT PKWY #200
City: WICHITA State: KS Zip: 67206-6602

LOCATION - Location ID: 317263

Location Name: YOUNG-62S50W Number: 35SWNW County:
Qtrqtr: SWN Sec: 35 Twp: 2S Range: 50W Meridian: 6
W
Latitude: 39.839067 Longitude: -102.951222

FACILITY - API Number: 05-121-00 Facility ID: 317263

Facility Name: YOUNG-62S50W Number: 35SWNW
Qtrqtr: SWN Sec: 35 Twp: 2S Range: 50W Meridian: 6
W
Latitude: 39.839067 Longitude: -102.951222

CORRECTIVE ACTIONS:

1 CA# 201485

Corrective Action: Comply with Rule 1004. Reclaim access road and reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date:

Response: CA COMPLETED

Date of Completion: 12/30/2025

Operator Comment: Please route to reclamation staff for consideration of final reclamation inspection and release of financial assurance for operator Stelbar Oil Corp Inc - 82470. Perimeter fencing has been removed. Access road does not require regrading with tracks only evident when driven on in sandy texture soil. Location complies with Rule 1004 final reclamation requirements.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please route to reclamation staff for consideration of final reclamation inspection and release of financial assurance for operator Stelbar Oil Corp Inc - 82470. Perimeter fencing has been removed. Access road does not require regrading with tracks only evident when driven on in sandy texture soil. Location complies with Rule 1004 final reclamation requirements.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kate Graves Signed: _____

Title: Technical Advisor Date: 1/14/2026 12:10:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404505696	FIR RESOLUTION SUBMITTED
404505836	Response and photos

Total Attach: 2 Files