

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403837900

Date Received:  
01/21/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<a href="mailto:rbucogccinspectionreports@chevron.onmicrosoft.com">rbucogccinspectionreports@chevron.onmicrosoft.com</a>
.		<a href="mailto:abbeynewby@chevron.com">abbeynewby@chevron.com</a>
.		<a href="mailto:rbucogccinspectionreports@chevron.onmicrosoft.com">rbucogccinspectionreports@chevron.onmicrosoft.com</a>
.		<a href="mailto:abbeynewby@chevron.com">abbeynewby@chevron.com</a>

ECMC INSPECTION SUMMARY:

FIR Document Number: 709400861

Inspection Date: 03/04/2024

FIR Submit Date: 03/14/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PETRO-CANADA RESOURCES (USA) INC

Company Number: 72085

Address: 5455 BRIGHTON BLVD

City: COMMERCE CITY State: CO Zip: 80022

LOCATION - Location ID: 376781

Location Name: DOWNING B-63S59W Number: 24NENW County: \_\_\_\_\_

Qtrqr: NENW Sec: 24 Twp: 3S Range: 59W Meridian: 6

Latitude: 39.780966 Longitude: -103.936970

FACILITY - API Number: 05-001-00 Facility ID: 376781

Facility Name: DOWNING B-63S59W Number: 24NENW

Qtrqr: NENW Sec: 24 Twp: 3S Range: 59W Meridian: 6

Latitude: 39.780966 Longitude: -103.936970

CORRECTIVE ACTIONS:

1 CA# 193137

Corrective Action: Comply with Rule 606 weeds

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 06/20/2024

Mowed location and removed fence. We plan on inner seeding the site later in the fall and added the location to maintenance and monitoring program.

Operator  
Comment:

ECMC Decision:

ECMC  
Representative:

**2** CA# 193138

Corrective Action: Comply with rule 1004.

Date: 04/01/2024

Response: CA COMPLETED

Date of Completion: 06/20/2024

Operator  
Comment:

Mowed location and removed fence. We plan on inner seeding the site later in the fall and added the location to maintenance and monitoring program. Filled in and bladed ruts in access road.

ECMC Decision:

ECMC  
Representative:

**3** CA# 193139

Corrective Action: Comply with rule 1004. Recontouring

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 06/20/2024

Operator  
Comment:

Mowed location and removed fence. Recontouring would cause more damage to established vegetation and landowner did not allow this to work to be done. We plan on inner seeding the site later in the fall and added the location to maintenance and monitoring program. Filled in and bladed ruts in access road.

ECMC Decision:

ECMC  
Representative:

**4** CA# 193140

Corrective Action: Comply with rule 1002 Stormwater Management

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 06/20/2024

Operator  
Comment:

We filled in and bladed out the ruts on the access road that is being used by other operators. We plan on inner seeding the site later in the fall and added the location to maintenance and monitoring program. Filled in and bladed ruts in access road.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Completed all 4 Corrective Actions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed:

Title: HSE

Date: 1/21/2026 7:27:07 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403837900	FIR RESOLUTION SUBMITTED
403837901	completed photos

Total Attach: 2 Files