

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2026

Submitted Date:

01/27/2026

Document Number:

713401193

FIELD INSPECTION FORM

Loc ID 316158 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10775
Name of Operator: KT RESOURCES LLC
Address: 3381 WESTBROOK LANE
City: HIGHLANDS State: CO Zip: 80129

Findings:

- 22 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen		adams@kt-res.com	
Baumgras, Dan		dan@kt-res.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232254	WELL	SI	03/01/2024	GW	103-09925	WRD UNIT 20-33	SI

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Lube oil tank on containment		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	1-800-288-0560/911		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds & weed debris near wellhead, pump jack and secondary containment presents a potential fire hazard		
Corrective Action:	Comply with CECMC rule 606	Date:	02/03/2026
Type	OTHER		
Comment:	Staining on location around Pump Jack, refer to photos		
Corrective Action:	Comply with CECMC rules 606 & 902	Date:	02/03/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Livestock & Barbed wire		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Lube oil tank on containment		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint					
Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment: Centralized containment					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

Paint					
Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment: Centralized containment					
Corrective Action:					Date:

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					
					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					
					Date:

Inspected Facilities

Facility ID: 232254 Type: WELL API Number: 103-09925 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						Light compaction
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containment
Berms						
		Compaction				

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 01/6/2026 at approximately 13:57 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at KT RESOURCES LLC WRD UNIT #20-33 PAD at Location ID #316158 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> Housekeeping - Weeds & weed debris near wellhead, pump jack and secondary containment presents a potential fire hazard with a CA date of 02/3/2026 Housekeeping - Staining on location around Pump Jack with a CA date of 02/3/2026 <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	01/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401194	713401193 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7428884