



00257064

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
D-028963

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
McCallum Unit

8. FARM OR LEASE NAME

9. WELL NO.
55

10. FIELD AND POOL, OR WILDCAT
McCallum/Pierre

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 2, T9N, R79W

12. COUNTY OR PARISH | 13. STATE
Jackson | Colorado

1. OIL WELL GAS WELL OTHER

JUN 09 1986

2. NAME OF OPERATOR
Conoco Inc.

COLO. OIL & GAS CONS. COMM.

3. ADDRESS OF OPERATOR
907 N. Poplar Casper, Wyoming 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1,670' FNL, 2,270' FWL (SE/NW)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

8,198' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANS

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to plug and abandon the subject well as follows:

- Run in hole with 2 joints of 1" tubing open ended to ±60' TD.
- Mix and pump 17 sacks Class "G" cement. Pull out of hole.
- Cut casing at 6' below ground level. Install dry hole marker, and restore location.



BLM-Craig(3) BLM-Kremmling(2) COGCC(2) File (SJM)

18. I hereby certify that the foregoing is true and correct

SIGNED *J. C. Thompson*

TITLE Administrative Supervisor

DATE June 2, 1986

(This space for Federal or State office use)

APPROVED BY *J. A. [Signature]*
CONDITIONS OF APPROVAL, IF ANY:

TITLE SUPR. PETROLEUM ENGINEER
Oil & Gas Cons. Comm

DATE JUN 11 1986

*See Instructions on Reverse Side

AR