



COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <i>115 - 06053</i>		LEASE NAME: <i>State 16-11-1</i>	
LOCATION: <i>NESW 16-10N-47W</i>		OPERATOR: <i>Peterson Energy Mgmt</i>	
DATE: <i>4-2-96</i>		INSPECTOR: <i>Ed Brinkley</i>	
Insp. Type: <i>SR</i>	Insp. Status: <i>DA</i>	PA: Y <input checked="" type="checkbox"/> N	Pass/Fail: P <input checked="" type="checkbox"/> F
		Viol.: <input checked="" type="checkbox"/> Y N	NOV: Y <input checked="" type="checkbox"/> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)	<i>R-pit open</i>	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)	<i>(Circled mark)</i>	
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	<i>Road and location requires leveling, disk & reseeding w/ straw.</i>	
Miscellaneous	<i>Called msg to Peterson 4-2-96</i>	

CORRECTIVE ACTION REQUIRED: *Reclaim, seed and restore site and road access. Repair fencing.*

Date Corrective Action Required By: *4-30-96* Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

APR 18 1996