



RECEIVED  
MAY 11 1976

RECEIVED  
MAR 23 1976

Application for Patented and Federal lands  
Application for State lands. COLO. OIL & GAS CONS.

5. LEASE DESIGNATION AND SERIAL NO. COMM. 8079S

6. IF INDIAN, ALLOTTEE OR TRIBE NAME 05706078

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

STATE

9. WELL NO. #16-1A REENTRY

10. FIELD AND POOL, OR WILDCAT WILDCAT

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA SEC. 16, T9N-R81W

### SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER DRY HOLE

2. NAME OF OPERATOR BURTON/HAWKS EXPLORATION Co., LTD.

3. ADDRESS OF OPERATOR P.O. BOX 359, CASPER WYOMING, 82602

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface 1960' FSL, 1750' FEL  
At proposed prod. zone 1660' FSL, 2430' FEL

14. PERMIT NO. 73-485

15. ELEVATIONS (Show whether DF, RT, CR, etc.) 8222' GL/8232' KB

12. COUNTY JACKSON

13. STATE COLORADO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON TEMPORARY <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

DVR	<input type="checkbox"/>
FJP	<input checked="" type="checkbox"/>
JAN	<input checked="" type="checkbox"/>
COM	<input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 12-30-75 THRU 1-8-76 WELL WAS NOT LOGGED.

12-31-75: SPOUDED 10:00 A.M. 12-30-75. DRILLED OUT PLUG AT BASE OF SURFACE CASING. ATTEMPTING TO WASH BOTTOM. HAVING TROUBLE @ 1518'. MUDDING UP.

1-5-76 HAVE WASHED TO BOTTOM. HEALED UP THE CAVING SHALE ZONE FROM 1500' TO 1856'. DEVELOPED A KEY-SEAT. GOING IN HOLE WITH KEY-SEAT REAMER. FOUND TOP OF PLUG AT 1856'

1-7-76 DRESSED PLUG TO 1900', STUCK 45' OFF BOTTOM. RAN FREE-POINT. PIPE STUCK CLOSE TO BIT. WENT IN WITH SHOT, BACKED PIPE OFF. LEFT 3 DRILL COLLARS AND BIT IN HOLE. WENT IN WITH JARS. UNABLE TO JAR LOOSE. WILL ATTEMPT TO SHOOT PIPE OPPOSITE BIT SUB AND RECOVER AS MUCH AS POSSIBLE AND ABANDON HOLE.

1-8-76 RIGGED DOWN. COULD NOT RECOVER FISH. LEFT 3 DRILL COLLARS, SUB, BIT AND BUMPER SUB IN HOLE. REMAINING PLUGS IN HOLE:

<u>4200-4080</u>	<u>40 SX. (DAKOTA-LAKOTA)</u>
<u>(SET IN 1975)</u>	<u>100 SX. (FRONTIER)</u>
<u>3400-3100</u>	<u>100 SX. (TOP NIOBRARA)</u>
<u>2200-1900</u>	

NO PLUGS WERE SET AT BASE OF SURFACE CASING OR AT SURFACE PENDING STUDY OF FEASIBILITY OF REENTERING AND WHIPSTOCKING FROM A SHALLOWER DEPTH.

18. I hereby certify that the foregoing is true and correct

SIGNED Robert E. Wellborn TITLE EXPLORATION MANAGER DATE 3-24-76  
ROBERT E. WELLBORN

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE March 20 1976

CONDITIONS OF APPROVAL, IF ANY:



[Handwritten mark]