



COLO
ATTN: Robin
E2 problem



CONSERVATION COMMISSION
ION INSPECTION REPORT

| | |
|---|--------------------------------|
| <input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION | 337 CAMBRIDGE STREET |
| <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | BRUSH, CO 80723 (970)-842-4465 |

| | |
|-------------------------|--|
| API No. 05- 121 - 5294 | LEASE NAME: Wiant |
| LOCATION: NWSE 33-35-49 | OPERATOR: Pease |
| DATE: 5-10-99 | INSPECTOR: ED BINKLEY MOBIL (970)-380-2683 |

| | | | | | |
|--------------|----------------|--|---|--|---|
| INSP TYPE SR | INSP STATUS PA | PA Y <input checked="" type="checkbox"/> N <input checked="" type="checkbox"/> | PASS/FAIL P <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> | VIOLATION Y <input checked="" type="checkbox"/> N <input type="checkbox"/> | NOV Y <input type="checkbox"/> N <input type="checkbox"/> |
|--------------|----------------|--|---|--|---|

| | | | | | | | | |
|---------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-------------------------------------|---------------------------------|----------------------------------|
| UIC VIOL TYPE | UA <input type="checkbox"/> | MI <input type="checkbox"/> | OP <input type="checkbox"/> | PA <input type="checkbox"/> | OT <input type="checkbox"/> | TBG/PKR LK <input type="checkbox"/> | CSG LK <input type="checkbox"/> | ALL UIC VIOLATIONS REQUIRE NOAVS |
|---------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-------------------------------------|---------------------------------|----------------------------------|

| | |
|---|--|
| Well ID Signs (Rule 210) <input type="checkbox"/> | Fences (Rule 604.C.(3), 1003.A) <input type="checkbox"/> |
|---|--|

| | | |
|---|--------------------------------------|--|
| Production Pits (Rule 902, 903, 904) EARTHEN PITS ONLY | PRODUCED WATER PITS TOTAL # _____ | OIL ACCUMULATION <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> |
| | SKIMMING/SETTLING PITS TOTAL # _____ | COVERED # _____ UNCOVERED # _____ |
| | SPECIAL PURPOSE PITS TOTAL # _____ | LINED # _____ UNLINED # _____ |
| | COMMENTS/SIZE _____ | |
| SENSITIVE AREA <input type="checkbox"/> YES <input type="checkbox"/> NO | | |

| | |
|--|--|
| Tank Battery Equipment (Rule 604) <input type="checkbox"/> | BURIED OR PARTIALLY BURIED VESSELS : #STEEL _____ #FIBERGLASS _____ #CONCRETE _____ #OTHER _____ |
|--|--|

| | |
|--|--|
| Fire Walls/Berms/Dikes (Rule 604) <input type="checkbox"/> | |
|--|--|

| | | |
|--|-----------|-------------|
| General Housekeeping (Rule 603.G) <input type="checkbox"/> | pits open | MAY 17 1999 |
|--|-----------|-------------|

| | |
|--|--|
| Spills (Oil/Water) (Rule 908) <input type="checkbox"/> | |
|--|--|

| | | |
|---|--|--|
| UIC ROUTINE INSPECTION FILL OUT FORM 21 WHEN WITNESSING MIT | INJ PRESSURE _____ PSIG T-C ANN PRESSURE _____ PSIG BRHD PRESSURE _____ PSIG | COMMENTS office 3300 Airport Road, Box A Boulder, CO 80301 |
|---|--|--|

| | |
|--|--|
| Drilling Well/Workover (Rule 315) <input type="checkbox"/> | Sombreno Ranches, Inc - Rex Ross Walker ✓ 5-12-99 303-442-0258 FAX 303-442-0380 |
|--|--|

| | |
|--|---|
| Surface Rehabilitation (Rule 317) <input type="checkbox"/> | Large pits open adjacent to site in grass land MAY/owner - Mark Bishop - Boulder |
|--|---|

| | |
|--|--|
| Miscellaneous <input type="checkbox"/> | L/O rep Mason King @ Cope-970 357-4245 info@sombreno.com - horse ranch- |
|--|--|

| | |
|---|----------------|
| CORRECTIVE ACTION REQUIRED: Close pits per work plan on FORM 27. Contour area and reseed with landowner seed requirements. Soil/condi froring is required due salt water contamination. | |
| Date Corrective Action Required By: 6-30-99 | Date Remedied: |

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.