

37. SUMMARY OF POROUS ZONES:
 SHOW ALL IMPORTANT ZONES OF POROSITY AND CONTENTS THEREOF; CORED INTERVALS; AND ALL DRILL-STEM TESTS, INCLUDING DEPTH INTERVAL TESTED, CUSHION USED, TIME TOOL OPEN, FLOWING AND SHUT-IN PRESSURES, AND RECOVERIES.

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
			Drilled to 3697 TD No Cores or DST'S P & A 15 Sax Cement Bottom of Surface Pipe 10 Sax Cement Top of surface Pipe

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Niobrara	2800	
Greenhorn	3370	
Bentonite	3550	
"D" Sand	3640	
"J" Sand	3670	
Total Depth	3697	