

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/05/2026

Submitted Date:

02/09/2026

Document Number:

713401218

FIELD INSPECTION FORM

Loc ID 316695 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 35095
Name of Operator: GRAND VALLEY RESOURCES INC
Address: P O BOX 39
City: RANGELY State: CO Zip: 81648

Findings:

- 21 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Roberts, James		j75rober@blm.gov	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Heil, John		john.heil@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
Fix, Earl	(970) 675-2639	budruff1@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232259	WELL	PR	12/04/2014	OW	103-40003	ANDERSON-GOVERNMENT 17-1	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Operator Emergency Contact Number is not in service - 970-675-2639		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Production tank labels not legible & lack required labeling/not in compliance with CECMC rules, refer to photos		
Corrective Action:	Comply with CECMC rule 605		Date: 03/09/2026
Emergency Contact Number:			
Comment:	Operator Emergency Contact Number is not in service - 970-675-2639 or 911		
Corrective Action:	Comply with CECMC rule 605		Date: 02/05/2026
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris on location, refer to photos		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Weeds/undesirable plant species at multiple areas near surface flowline from wellhead to tank battery and surrounding secondary containment & production tanks presents a potential fire hazard, refer to photos		
Corrective Action:	Comply with CECMC rule 606		Date: 02/05/2026
Type	UNUSED EQUIPMENT		
Comment:	Unused unload line not in service near tank battery not necessary for use on location and additionally is open ended piping/wildlife hazard/available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC Rules 606 & 602		Date: 03/09/2026
Type	OTHER		
Comment:	Staining on location near wellhead, multiple areas near surface flowline from wellhead to tank battery & inside secondary containment. Additionally Weeds/undesirable plant species around production equipment presents a potential fire hazard, refer to photos Called operator emergency number for immediate CA at time of inspection and emergency contact number is not in service.		
Corrective Action:	Comply with CECMC rules 606 & 902		Date: 02/05/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Pipe rail fence		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Horizontal Heater Treater	# 1				
		Comment:			
		Corrective Action:		Date:	
Bird Protectors	# 1				
		Comment:			
		Corrective Action:		Date:	
Deadman # & Marked	# 1				
		Comment: Improperly marked deadman - All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.			
		Corrective Action:		Date:	
Ancillary equipment	# 1				
		Comment: Gas scrubber			
		Corrective Action:		Date:	
Pump Jack	# 1				
		Comment:			
		Corrective Action:		Date:	
Other	# 4				
		Comment: Unused flowlines lack lockout tagout (OOSLAT)			
		Corrective Action: Comply with CECMC Rule 1101		Date: 02/15/2026	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	500 BBLs	STEEL AST			
		Comment: Open ended piping/wildlife hazard/available for entry by wildlife, refer to photos				
		Tanks not equipped with telemetry				
		Corrective Action: Comply with CECMC rule 602		Date: 02/15/2026		

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	Unlined - Centralized containment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232259 Type: WELL API Number: 103-40003 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on pump jack - Fuel gas valve shut off to pump jack at time of inspection.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/24/2025 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Bradenhead inaccessible, refer to photos

02/18/2026

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per rule 419

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						Light compaction
		Compaction				
		Ditches				Light compaction
Ditches						

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 02/5/2026 at approximately 14:28 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD at Location ID #316695 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Emergency Contact Number - Operator Emergency Contact Number is not in service with a CA date of 02/5/2026 2. Housekeeping - Weeds/undesirable plant species at multiple areas near surface flowline from wellhead to tank battery and surrounding secondary containment & production tanks presents a potential fire hazard with a CA date of 02/5/2026 3. Housekeeping - Staining on location with a CA date of 02/5/2026 4. Equipment - Unused flowlines lack lockout tagout (OOSLAT) with a CA date of 02/15/2026 5. Tanks and Berms - Open ended piping/wildlife hazard/available for entry by wildlife with a CA date of 02/15/2026 6. Inspected Facilities - Bradenhead inaccessible with a CA date of 02/18/2026 7. Signs/Marker - Production tank labels not legible & lack required labeling/not in compliance with CECMC rules with a CA date of 03/9/2026 8. Housekeeping - Unused equipment on location with a CA date of 03/9/2026 <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	<p>popejoyd</p>	<p>02/08/2026</p>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404537398	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7442576
713401219	713401218 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7442575