

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/10/2026

Document Number:

716301955

FIELD INSPECTION FORM

Loc ID 309395 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections
B WARD, GIENA		gward@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294315	WELL	PR	07/10/2008	CBM	071-09478	GOLDEN EAGLE 34-13	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4, 5 & 6: area of impacted soil near wellhead appears to be from leaking hydraulic hoses. PHOTO 7, 8 & 9: area of impacted soil near compressor appears to be from leaking equipment over an extended period of time.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.	Date:	02/23/2026
Type	TRASH		
Comment:	PHOTO 10 trash on location.		
Corrective Action:	Remove all trash on and around location per rule 606.	Date:	02/23/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	is accessible		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	30 bbl produced water/used oil tank		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	form 4 vacuum sudry doc #402007225		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 294315 Type: WELL API Number: 071-09478 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/24/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: PHOTO 11: oily waste in prime mover engine skid without wildlife protections in place.

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. this equipment is leaking so bad in should be taken out of service until leaks are repaired. immediate action is required.

Date: 02/11/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Date: 2/10/2026 Time: 12:57 Operator: Ogris Operating LLC.10758 Location: Golden Eagle 34-13 API# 05-071-09478 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: Impacted oils in verious points around location, rule 1002,. (2).D. ca date 2/23/2026. trash, rule 606, ca date 2/23/2026. Oily waste in prime mover engin skit, RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. this equipment is leaking so bad in should be taken out of service until leaks are repaired. Ca date 2/11/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	02/10/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404540599	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7445454
716301956	insp. photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7445442