

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2026

Submitted Date:

02/18/2026

Document Number:

721100152

**FIELD INSPECTION FORM**

Loc ID 313621 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LLC  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	
General		CO2Source_Regulatory@kindermorgan.com	<a href="#">All SW field inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295333	WELL	TA	12/01/2019	CO2	083-06646	HF 3	TA

**General Comment:**

At 4:30 PM on Monday, February 16, 2016, southwest compliance specialist Jamie Blair performed a compliance inspection and audit on Kinder Morgan HF-3. The well is temporarily abandoned. No corrective actions were identified.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Road is in good shape. Check dams and culverts along road are okay.		
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	At pad entrance. Photo 1.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	970-882-5522 = 24 Hour 911 = 911		Date:
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	4 strand barbed wire and gate.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Other	# 1		corrective date
Comment:	wellhead.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	accessible		
Corrective Action:			Date:
Type: Deadman # & Marked	# 0		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	annular vent behind pipe barricade.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	horizontal portion removed, riser has OOSLAT.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 295333 Type: WELL API Number: 083-06646 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: 10/15/2025 MIT date

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/31/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
		Check Dams	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100153	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453454">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453454</a>