

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2026

Submitted Date:

02/18/2026

Document Number:

716301990

FIELD INSPECTION FORM

Loc ID 307747 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256444	WELL	PR	11/16/2003	CBM	071-06901	INDY 32-34	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 257655 Lat: 37.216781 Long: -104.872720

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: **PIT COORDINATES ARE INACCURATE ON PIT PERMIT**

Corrective Action: **FILE FORM 15 WITH CORRECT PIT COORDINATES**

Date: 03/18/2026

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Date: 2/18/2026 Time: 13:39 Operator: EVERGREEN NATURAL RESOURCES LLC 10705 Location: INDY 3234 API# 05-071-06901 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: PIT COORDINATES INACCURATE, CA DUE DATE 3/18/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	02/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301991	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7454177