

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404555875

Date Received:  
02/24/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>ZECHES. GIENA</u>		<u>GZECHES@OGRISOP.COM</u>
<u>BACA. DAVE</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 716301758  
Inspection Date: 11/25/2025 FIR Submit Date: 11/25/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: OGRIS OPERATING LLC Company Number: 10758  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**LOCATION** - Location ID: 309440

Location Name: NEW ELK-633S68W Number: 25NWNW County: LAS ANIMAS  
Qtrqtr: NWN Sec: 25 Twp: 33S Range: 68W Meridian: 6  
W  
Latitude: 37.147144 Longitude: -104.951726

**FACILITY** - API Number: 05-071- -00 Facility ID: 295029

Facility Name: NEW ELK Number: 25-04  
Qtrqtr: NWN Sec: 25 Twp: 33S Range: 68W Meridian: 6  
W  
Latitude: 37.147144 Longitude: -104.951726

**CORRECTIVE ACTIONS:**

**1** CA# 209649

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002. (2).D. this is the 2nd notice for this corrective action, immediate action is required.

Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 02/23/2026

THE IMPACTED SOIL NEAR THE COMPRESSOR SKID HAS BEEN REMOVED FROM LOCATION AND

Operator Comment: REPLACED WITH FRESH PAD MATERIAL. THE COMPRESSOR SKID HAS BEEN CLEANED AND MECHANICAL MAINTENANCE HAS BEEN PERFORMED TO ALL OPERATING EQUIPMENT

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

2 CA# 209650

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 11/26/2025

Response: CA COMPLETED

Date of Completion: 02/23/2026

Operator Comment: THE IMPACTED SOIL NEAR THE COMPRESSOR SKID HAS BEEN REMOVED FROM LOCATION AND REPLACED WITH FRESH PAD MATERIAL. THE COMPRESSOR SKID HAS BEEN CLEANED AND MECHANICAL MAINTENANCE HAS BEEN PERFORMED TO ALL OPERATING EQUIPMENT

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: \_\_\_\_\_

Title: ENVIRONMENTAL

Date: 2/24/2026 12:07:30 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404555875	FIR RESOLUTION SUBMITTED
404555885	PHOTO LOG

Total Attach: 2 Files