

103-08265



01900328

DONALD C. SLAWSON
OIL PRODUCER
ROCKY MOUNTAIN DIVISION
SUITE 905 COLORADO NATIONAL BUILDING
950 17TH STREET
DENVER, COLORADO 80202

RECEIVED

JUL 13 1978

TERRY COOPER
DIVISION MANAGER
J. LLOYD LOTSPEICH
DIVISION LANDMAN

COLO. OIL & GAS CONS. COMM.

TELEPHONE (303) 573-0836

July 12, 1978

Chandler & Associates, Inc.
1401 Denver Club Building
Denver, CO 80202

Attention: Mr. Dick Veghte

RE: Donald C. Slawson Federal 9-4
NENWSW Sec. 9, T2S, R101W
Cathedral Field
Rio Blanco Co. Colorado

DVR
FJP
HHM
JAM
JJD
RLS
CCM

Dear Dick;

In accordance with our telephone conversation, attached are survey plat and topographical map of our proposed Federal 9-4 well. The Cathedral Field spacing order provides that any well drilled closer than 600 feet to a 160-acre boundary requires the approval of the offsetting and cornering 160-acre tract owners. Because of terrain conditions, we desire to drill the location for the Southwest quarter of Section 9 730' from the West line and 2333' from the South line.

I would appreciate a letter directed to the Colorado Oil and Gas Commission (copy to Slawson) from Chandler and Associates as owner of the East half of Section 8, indicating that you have no objections to this location.

As you know this is a federal lease, and in order to complete all the paper work, we would appreciate this document as soon as convenient.

Yours very truly,

A. H. "Bud" Hurley, Jr.
Division Operations Manager

AHH:ah
Encl:

cc: D. V. Rogers