

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404558019

Date Received:
02/25/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>BACA, DAVE</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>
<u>ZECHES, GIENA</u>		<u>gZECHES@ogrisop.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 716301926
Inspection Date: 01/08/2026 FIR Submit Date: 01/08/2026 FIR Status: _____

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 308665

Location Name: GOLDEN EAGLE-633S67W Number: 21NWSE County: LAS ANIMAS
Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.156690 Longitude: -104.888730

FACILITY - API Number: 05-071-00 Facility ID: 278286

Facility Name: GOLDEN EAGLE Number: 21-10
Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.156690 Longitude: -104.888730

CORRECTIVE ACTIONS:

1 CA# 210342

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.

Date: 01/08/2026

Response: CA COMPLETED Date of Completion: 02/24/2026

Operator Comment: THE ENGINE SKID HAS BEEN CLEANED AND ALL STAINED SOIL HAS BEEN REMOVED FROM LOCATION. FRESH PAD MATERIAL HAS BEEN ADDED. ALL OPERATING EQUIPMENT HAS RECEIVED MECHANICAL MAINTENANCE.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 210343

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.

Date: 01/08/2026

Response: CA COMPLETED

Date of Completion: 02/24/2026

Operator Comment: THE DRIPPING LEAK HAS BEEN STOPPED AND PACKING ON THE WELL HEAD TIGHTENED. THE IMPACED SOIL HAS BEEN REMOVED FROM AROUND THE WELL HEAD AND FRESH PAD MATERIAL ADDED.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 210344

Corrective Action: POST SIGN PER RULE 605.

Date: 02/08/2026

Response: CA COMPLETED

Date of Completion: 02/24/2026

Operator Comment: THE API# AND EMERGENCY CONTACT INFO HAVE BEEN POSTED ON THE METER HOUSE.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 2/25/2026 2:04:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404558019	FIR RESOLUTION SUBMITTED
404558031	PHOTO LOG

Total Attach: 2 Files