

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404558167

Date Received:
02/25/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ZECHES, GIENA		gZECHES@ogrisop.com
BACA, DAVE	719-859-4066	dbaca@ogrisop.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 716301955
Inspection Date: 02/10/2026 FIR Submit Date: 02/10/2026 FIR Status:

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 309395

Location Name: GOLDEN EAGLE-633S67W Number: 34SWSW County: LAS ANIMAS
Qtrqtr: SWS Sec: 34 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.122722 Longitude: -104.882977

FACILITY - API Number: 05-071-00 Facility ID: 294315

Facility Name: GOLDEN EAGLE Number: 34-13
Qtrqtr: SWS Sec: 34 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.122722 Longitude: -104.882977

CORRECTIVE ACTIONS:

1 CA# 210902

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D.

Date: 02/23/2026

Response: CA COMPLETED Date of Completion: 02/24/2026

THE HYDRAULIC HOSES HAVE BEEN REPLACED AND ALL OPERATING EQUIPMENT HAS RECEIVED MECHANICAL MAINTENANCE. THE IMPACTED SOIL HAS BEEN REMOVED FROM LOCATION AND

Operator Comment: REPLACED WITH FRESH PAD MATERIAL.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 210903

Corrective Action: Remove all trash on and around location per rule 606.

Date: 02/23/2026

Response: CA COMPLETED

Date of Completion: 02/24/2026

Operator Comment: THE TRASH HAS BEEN REMOVED FROM LOCATION.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 210904

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. this equipment is leaking so bad in should be taken out of service until leaks are repaired. immediate action is required.

Date: 02/11/2026

Response: CA COMPLETED

Date of Completion: 02/24/2026

Operator Comment: THE COMPRESSOR SKID HAS BEEN CLEANED AND RECEIVED MECHANICAL MAINTENANCE. THE IMPACTED SOIL HAS BEEN REMOVED FROM LOCATION AND REPLACED WITH FRESH PAD MATERIAL

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETAILS

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 2/25/2026 2:47:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404558167	FIR RESOLUTION SUBMITTED
404558183	PHOTO LOG

Total Attach: 2 Files