

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404561833

Date Received:
03/02/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840
Name of Operator: ABUNDANCE ENERGY SERVICES LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
		<u>sjbcompliance@abundance-energy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714003475
Inspection Date: 02/03/2026 FIR Submit Date: 02/23/2026 FIR Status: _____

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 493209

Location Name: Hanh CTB Tank Battery Number: 493209 County: _____
Location
Qtrqtr: SWSE Sec: 40 Twp: 33N Range: 8W Meridian: 6
Latitude: 37.098421 Longitude: -107.701797

FACILITY - API Number: 05-067-00 Facility ID: 493209

Facility Name: Hanh CTB Tank Battery Number: 493209
Location
Qtrqtr: SWSE Sec: 40 Twp: 33N Range: 8W Meridian: 6
Latitude: 37.098421 Longitude: -107.701797

CORRECTIVE ACTIONS:

1 CA# 211107

Corrective Action: Maintain berms per rule 603. Date: 03/02/2026

Response: CA COMPLETED Date of Completion: 02/27/2026

Operator Comment: The secondary containment berm liner surrounding the water tank has been repaired. We would like to note that this location is a midstream asset and services gathering line pigging operations.

ECMC Decision: _____

ECMC
Representative:

2 CA# 211108

Corrective Action: Update labels per rule 605.

Date: 03/23/2026

Response: CA COMPLETED

Date of Completion: 02/27/2026

Operator Comment: Water tank labels have been updated to reflect the current operator. We would like to note that this location is a midstream asset and services gathering line pigging operations.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached remedial report.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed:

Title: Engineering Analyst

Date: 3/2/2026 7:20:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404561833	FIR RESOLUTION SUBMITTED
404561834	Remedial Report

Total Attach: 2 Files