

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404458249

Date Received:  
03/05/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10773  
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC  
Address: 5251 DTC PKWY STE 950  
City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Smith, Sydney</u>	<u>303-910-4511</u>	<u>ssmith@fundareresources.com</u>
<u>Parrish, Melissa</u>	<u>970-397-3896</u>	<u>mparrish@fundareresources.com</u>
<u>Krystal Heibel</u>		<u>krystal.heibel@state.co.us</u>
<u>TRUITT, J CODY</u>	<u>281-513-0697</u>	<u>ctruitt@fundareresources.com</u>
<u>Kyle Waggoner</u>		<u>kyle.waggoner@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100584  
Inspection Date: 10/22/2025 FIR Submit Date: 11/06/2025 FIR Status:

Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC Company Number: 10773  
Address: 5251 DTC PKWY STE 950  
City: GREENWOOD VILLAGE State: CO Zip: 80111

LOCATION - Location ID: 330643

Location Name: BRENNAN-610N58W Number: 32NWNW County:  
Qtrqtr: NWN Sec: 32 Twp: 10N Range: 58W Meridian: 6  
Latitude: 40.800164 Longitude: -103.895107

FACILITY - API Number: 05-123-00 Facility ID: 330643

Facility Name: BRENNAN-610N58W Number: 32NWNW  
Qtrqtr: NWN Sec: 32 Twp: 10N Range: 58W Meridian: 6  
Latitude: 40.800164 Longitude: -103.895107

CORRECTIVE ACTIONS:

1 CA# 209237

Corrective Action: Comply with Rule 606 Date: 11/12/2025

Response: CA COMPLETED Date of Completion: 11/11/2025

Operator Comment: In Accordance With Rule 606 - Trash Cleaned Up, Removed & Properly Disposed Of - Please See Attached Photo Document

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 209238

Corrective Action: Install or update sign to comply with Rule 605.a. Date: 12/22/2025

Response: CA COMPLETED Date of Completion: 12/02/2025

Operator Comment: In Accordance With Rule 605.a. - Signage Was Updated To Reflect Operator Fundare Resources Company - Please See Attached Photo Documentation.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 209239

Corrective Action: Repair burrowing surrounding the wellhead Date: 11/20/2025

Response: CA COMPLETED Date of Completion: 11/19/2025

Operator Comment: Burrowing Around Wellhead Has Been Backfilled In Accordance With Rules & Regulations At Wellhead - Please See Attached Photo Documentation

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melissa Parrish

Signed: \_\_\_\_\_

Title: Production Compliance Reg

Date: 3/5/2026 8:50:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404567287	Form Resolution Document Number 404458249 To Document Number 709100584 - Brennan 1

Total Attach: 1 Files