



[!] Re: TEP Rocky Mountain LLC - CPW Consultation - P&A and Casing Repair - Savage PA 331-9 (05-045-19722), FEDERAL RGU 14-16-198 (05-103-10759)

From Neumann - DNR, Danielle <danielle.neumann@state.co.us>  
Date Thu 3/5/2026 12:44 PM  
To Progressive <progressive@flywheelenergy.com>  
Cc Adam Tankersley <Adam.Tankersley@flywheelenergy.com>

DANGER!: This external sender has not been verified  
Hi Blythe,

Thank you for the opportunity to review the proposed work and best management practices. CPW does not have additional requests or concerns with this work.

Thank you,

On Thu, Mar 5, 2026 at 9:20 AM Progressive <progressive@flywheelenergy.com> wrote:

Good morning, Danielle,  
TEP is planning a P&A & a casing repair on the subject wells listed below.

Under ECMC Rule 312, operators are required to consult with CPW when non-routine maintenance operations are planned, which includes well repairs and plugging operation. We have included the identified HPHs associated with the location and are planning to begin operations upon approval by ECMC.

As a part of this process, we are required to attach any agreed upon BMPs and correspondence between CPW and the operator documenting consultation. To ensure proper well operations, TEP has proposed the Best Management Practices listed below for implementation during planned activities to minimize potential impacts to wildlife. If additional BMPs are necessary, please let us know.

Pad Name and Number	Well Number	API	Surface Ownership	Mineral Ownership	Type of work	Rule 1202.c(1) Habitats	Rule 1202.d Habitats	Rule 309.e Habitats	Federal Critical Habitats
Savage PA 34-4 (334654)	Savage PA 331-9	05-045-19722	FEE	FEE	P&A	None	Elk Severe Winter Range Elk Winter Concentration Area Mule Deer Winter Concentration Area Mule Deer Severe Winter Range	None	None

**Associated**

**BMP's**

**Mule Deer and Elk BMPs**

- Wildlife – Minimization:** To minimize the potential for wildlife related traffic accidents, TEP has implemented speed restrictions for all lease roads and requires that all TEP employees and contractors adhere to these posted speed restrictions.
- Wildlife – Minimization:** TEP will make best efforts to minimize operations at these location during winter months by conducting operations, when possible, between 9:00am to 4:00pm when wildlife activity minimal.
- Wildlife –Minimization:** TEP will minimize vehicle numbers and traffic by carpooling to the site whenever possible

Pad Name and Number	Well Number	API	Surface Ownership	Mineral Ownership	Type of work	Rule 1202.c(1) Habitats	Rule 1202.d Habitats	Rule 309.e Habitats	Federal Critical Habitats
FEDERAL RGU- 61S98W 16SWSW (316544)	FEDERAL RGU 14-16-198	05-103-10759	FED	FED	Casing Repair	None	Mule Deer Migration Corridor	None	None

**Associated**

**BMP's**

**Mule Deer and Elk BMPs**

- Wildlife – Minimization:** To minimize the potential for wildlife related traffic accidents, TEP has implemented speed restrictions for all lease roads and requires that all TEP employees and contractors adhere to these posted speed restrictions.
- Wildlife – Minimization:** TEP will make best efforts to minimize operations at these location during winter months by conducting operations, when possible, between 9:00am to 4:00pm when wildlife activity minimal.
- Wildlife –Minimization:** TEP will minimize vehicle numbers and traffic by carpooling to the site whenever possible

Thank you!

Blythe Befus



TEP Rocky Mountain  
Regulatory Analyst (Contractor)  
[progressive@flywheelenergy.com](mailto:progressive@flywheelenergy.com)  
o: (303) 309-1657

--  
Dani Neumann  
NW Region Energy Liaison  
(She/her/hers)

State Employees Resource: [NW Region Land Use Spreadsheet](#)



C 970.366.1223  
0088 Wildlife Way  
Glenwood Springs, CO, 81601  
[danielle.neumann@state.co.us](mailto:danielle.neumann@state.co.us) | [cpw.state.co.us](http://cpw.state.co.us)



