

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404464267

Date Received:
03/06/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303424
Inspection Date: 02/06/2025 FIR Submit Date: 02/10/2025 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335275

Location Name: DOE-66S95W Number: 28SWNE County: _____
Qtrqtr: SWNE Sec: 28 Twp: 6S Range: 95W Meridian: 6
Latitude: 39.497159 Longitude: -107.999993

FACILITY - API Number: 05-045-00 Facility ID: 335275

Facility Name: DOE-66S95W Number: 28SWNE
Qtrqtr: SWNE Sec: 28 Twp: 6S Range: 95W Meridian: 6
Latitude: 39.497159 Longitude: -107.999993

CORRECTIVE ACTIONS:

1 CA# 202460

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/26/2025

Response: CA COMPLETED Date of Completion: 03/12/2025

Operator Comment: Vehicle tracking and sediment transportation has been mitigated through placement of 1 1/2" screened rock to gravel location. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Vehicle tracking and sediment transportation has been mitigated through placement of 1 1/2" screened rock to gravel location. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Supervisor

Date: 3/6/2026 6:55:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404464267	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files