

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404572348

Date Received:
03/09/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 719200893
Inspection Date: 02/27/2026 FIR Submit Date: 03/04/2026 FIR Status: _____

Inspected Operator Information:

Company Name: QB ENERGY OPERATING LLC Company Number: 10844
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334834

Location Name: PITMAN-67S92W Number: 18NWNE County: _____
Qtrqtr: NWNE Sec: 18 Twp: 7S Range: 92W Meridian: 6
Latitude: 39.451790 Longitude: -107.706410

FACILITY - API Number: 05-045-00 Facility ID: 334834

Facility Name: PITMAN-67S92W Number: 18NWNE
Qtrqtr: NWNE Sec: 18 Twp: 7S Range: 92W Meridian: 6
Latitude: 39.451790 Longitude: -107.706410

CORRECTIVE ACTIONS:

1 CA# 211326

Corrective Action: Comply with Rule 603.o. Date: 03/18/2026

Response: CA COMPLETED Date of Completion: 03/09/2026

Operator Comment: Patched holes in secondary containment liner to comply with ECMC rule 603.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: _____

Title: Compliance

Date: 3/9/2026 3:36:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404572348	FIR RESOLUTION SUBMITTED
404572353	Liner Repair

Total Attach: 2 Files