

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404573254

Date Received:  
03/10/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Baca, Dave</u>	<u>719-846-4066</u>	<u>dbaca@ogrisop.com</u>
<u>.Ogris</u>	<u>719-220-4041</u>	<u>gzeches@ogrisop.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 698708255  
Inspection Date: 10/31/2025 FIR Submit Date: 10/31/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 307896

Location Name: HILL RANCH-634S67W Number: 22NWSW County: LAS ANIMAS  
Qtrqtr: NWS Sec: 22 Twp: 34S Range: 67W Meridian: 6  
W  
Latitude: 37.066730 Longitude: -104.880610

FACILITY - API Number: 05-071- -00 Facility ID: 259238

Facility Name: HILL RANCH Number: 22-12 V  
Qtrqtr: NWS Sec: 22 Twp: 34S Range: 67W Meridian: 6  
W  
Latitude: 37.066730 Longitude: -104.880610

CORRECTIVE ACTIONS:

**1** CA# 209038

Corrective Action: Comply with rule 605 Date: 11/07/2025

Response: CA COMPLETED Date of Completion: 03/06/2026

Operator Comment: THE ENGINE WITHIN THE SOUND WALLS HAS BEEN REPAIRED AND PLACED BACK INTO SERVICE. THE TEMPORARY LIQUID RING COMPRESSOR HAS BEEN REMOVED FROM LOCATION. ALL OPERATING EQUIPMENT HAS RECEIVED MECHANICAL MAINTENANCE AND THE SELF INSPECTION PROCEDURE HAS BEEN REVIEWED.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 209039

Corrective Action: Comply with rule 605

Date: 11/07/2025

Response: CA COMPLETED

Date of Completion: 03/06/2026

Operator  
Comment:

THE SOIL STAINS AT THE WELL HEAD HAVE BEEN REMOVED AND REPLACED WITH FRESH PAD MATERIAL. THE HYDRAULIC HOSES/CONNECTIONS HAVE BEEN REPLACED.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETIALS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: \_\_\_\_\_

Title: ENVIRONMENTAL

Date: 3/10/2026 10:17:02 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404573254	FIR RESOLUTION SUBMITTED
404573258	PHOTO LOG

Total Attach: 2 Files