

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2026

Submitted Date:

03/05/2026

Document Number:

713302539

FIELD INSPECTION FORM

Loc ID 327605 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247120	WELL	PR	03/01/2019	GW	123-14917	OCOMA 31-19	PR

General Comment:

[well site inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	missing		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	04/06/2026

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Ancillary equipment	# 2		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 247120 Type: WELL API Number: 123-14917 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 08/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection, Location: Ocoma 31-19 Operator: KPK API#: 123-14917 County: Weld During this inspection the following possible compliance issues were observed:</p> <p>Sign, Rule 605g, corrective action date 4-6-2026</p> <p>Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	03/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404568850	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7470431
713302540	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7470429