

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404171326

Date Received:
03/16/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

14 of 14 CAs from the FIR responded to on this Form

14 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|-------------------|-------------------------------|----------------------------------|
| Kennedy, Herschel | (719) 767-3401/(719) 671-3787 | hkennedy@cogc.com |
| Bob Redweik | (281) 891-1550 | bredweik@cogc.com |
| Joel Mason | | joel.mason@absarokasolutions.com |
| Krystal Heibel | | krystal.heibel@state.co.us |
| Harris, Debra | (281) 891-1576/(970) 799-1103 | dharris@cogc.com |
| Kyle Waggoner | | kyle.waggoner@state.co.us |
| Kym Shure | | kym.schure@state.co.us |
| WARD, SHARON | 281-891-1556 | sward@cogc.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100292
Inspection Date: 05/23/2024 FIR Submit Date: 06/04/2024 FIR Status:

Inspected Operator Information:

Company Name: CITATION OIL & GAS CORP Company Number: 17180
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

LOCATION - Location ID: 312320

Location Name: SINDT-610N52W Number: 31SESW County:
Qtrqr: SESW Sec: 31 Twp: 10N Range: 52W Meridian: 6
Latitude: 40.790577 Longitude: -103.223836

FACILITY - API Number: 05-075- -00 Facility ID: 312320

Facility Name: SINDT-610N52W Number: 31SESW
Qtrqr: SESW Sec: 31 Twp: 10N Range: 52W Meridian: 6
Latitude: 40.790577 Longitude: -103.223836

CORRECTIVE ACTIONS:

1 CA# 195579

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d.(1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.

Date: 06/06/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Form 19 initial document #403816314 submitted 6/7/2024, accepted 6/11/2024, work occurred under spill / release ID #486946
Transferred to a form 27, document #403888845. Pending ECMC approval.

ECMC Decision: _____

ECMC Representative:

2 CA# 195580

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d.(1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.

Date: 06/06/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Form 19 initial document #403816314 submitted 6/7/2024, accepted 6/11/2024, work occurred under spill / release ID #486946
Transferred to a form 27, document #403888845. Pending ECMC approval.

ECMC Decision: _____

ECMC Representative:

3 CA# 195581

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 07/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: All spills at the location have been cleaned up in compliance with Rule 912 .a. Please see attachment A for documentation.

ECMC Decision: _____

ECMC Representative:

4 CA# 195582

Corrective Action: Inspect, maintain and repair tanks to comply with rule 609.b. Immediately remove oily waste.

Date: 07/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Tanks were pressure washed to remove all oily waste and stains. What remains (deep staining) cannot be removed with pressure washing and will be painted over. See attachment A for photograph documentation.

ECMC Decision: _____

ECMC Representative:

5 CA# 195583

Corrective Action: Remove produced liquid hydrocarbons from the earthen pit or reservoir immediately per Rule 909.d.

Date: 06/05/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Liquids have been removed from the earthen pit (an inspection by ECMC rep on July 15,2025 verifies).

ECMC Decision:

ECMC Representative:

6 CA# 195584

Corrective Action: Install or repair wildlife protection equipment.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: All secondary containment pans on site have had chicken wire installed over them to protect wildlife. See attachment A for photographs.

ECMC Decision:

ECMC Representative:

7 CA# 195585

Corrective Action: Handle waste in accordance with Rule 905 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Stained equipment, stained soils, and all areas of hardened E&P waste have been removed from location. See photos of cleaned soils, equipment, and bagged waste in attachment A.

ECMC Decision:

ECMC Representative:

8 CA# 195586

Corrective Action: Comply with Rule 606

Date: 06/11/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: All trash and weeds at location have been cleaned up. See attachment A for photographs.

ECMC Decision:

ECMC Representative:

9 CA# 195587

Corrective Action: Comply with Rule 606

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

All trash and weeds at location have been cleaned up. See attachment A for photographs.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

10 CA# 195588

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 03/10/2026

Operator Comment: Further investigation is being completed as the current operator of the Arthur Sindt #2-WD Pit is Meritage Energy Partners. Citation will determine the feasibility of a Form 9 transfer of ownership or application of a Form 15 Pit Report.

ECMC Decision:

ECMC
Representative:

11 CA# 195589

Corrective Action: Comply with Rule 606

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: All trash, weeds, and unnecessary equipment have been removed from site. See attachment A for photos.

ECMC Decision:

ECMC
Representative:

12 CA# 195590

Corrective Action: Install sign to comply with Rule 605.a.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Signage has been installed to comply with rule 605 .a. See attachment A for photographic documentation.

ECMC Decision:

ECMC
Representative:

13 CA# 195591

Corrective Action: Comply with 913.b(5)B.i. to fence to prevent access when sites are not attended.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator Comment: Fence has been repaired and fortified to comply with rule 913.b (5) B.i. Verified by ECMC inspector on July 15, 2025.

ECMC Decision:

ECMC
Representative:

14 CA# 195592

Corrective Action: Install sign to comply with Rule 605.h.

Date: 07/04/2024

Response: CA COMPLETED

Date of Completion: 07/30/2025

Operator
Comment: Signage on site has been updated in compliance with Rule 605.h.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bob Redweik

Signed: _____

Title: VP – EHS and Regulatory

Date: 3/16/2026 7:31:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|------------------------|--------------------------|
| 404171326 | FIR RESOLUTION SUBMITTED |
| 404574449 | Photo Documentation |

Total Attach: 2 Files